


ZKBioSecurity – How to clear the admin on the device

Following are steps to take when clear admin on a device.

Device > Device

Select the device in the tick box you want to clear the administration on.

Select-control and in the drop-down menu select clear Administrator Permission



Select ok

